

FIRMWARE UPDATED CONTENT AND FUNCTION DESCRIPTION

WS-TB-1

V1.01.05

Version	Upgraded	Firmware Version	Date
V1.0	1. Improve APP control function.	WS_TB_1_FW_V1.00.06	2021-10-27
V2.0	1. Fix the problem that the single color fixtures can't be controlled when adding both single color fixtures and bi-color ones in one group. 2. Fix the bug in special effects control. 3. Fix the function of FADE.	WS_TB_1_FW_V1.01.05	2022-3-9

- **WS_TB_1_FW_V1.00.06**

Updated Content Description:

1. Improve APP control function.

- **WS_TB_1_FW_V1.01.05**

Updated Content Description:

1. Fix the problem that the single color fixtures can't be controlled when adding both single color fixtures and bi-color ones in one group.
2. Fix the bug in special effects control.
3. Fix the function of FADE.